

Rub marks on the roller door shutters

Occasionally, there is discussion about rub spots on the roller door surfaces, particularly on the inner side. They occur because the profiles of a roller door shutter lie on each other during winding, resulting in unavoidable rubbing.

They are common in an operating roller door and considered completely normal. The rub spots do not affect either the operational reliability or the functioning of the doors, but only their appearance.

(see statement of Prof. Dr.-Ing. L. Knepper in Steuff, Das Rolltor, 2. Auflage, Werner Verlag)